

LCC Ventilation Testing Deficiencies and Project Notes:

Student Services Building #1:

- 1. TU-5: Controls not communicating.
- **2. EF-1:** Serves Men's Rm. No. 117, Women's Rm. 119 and Janitor Rm. 118. Design is 810 CFM, actual airflow achieved is 230 CFM.
- 3. EF-3: Serves Men's Rm. No. 211. Design is 400 CFM, actual airflow achieved is 250 CFM.

Once TU-5 is operating correctly we will be 100% complete. We suggest EF-1 and EF-3 fan belts be verified and duct inspected for lint and debris.

Administration Building #3:

- 1. Min OSA: We need the required minimum OSA. Will 25% of original design CFM be sufficient?
- 2. MZ-5: We noted zone no. 1 cooling control zone damper does not fully close when stat is thrown to heat. Zone no. 1 had an access plate to verify the damper position. The other zones do not have any access. Suggest all zones be temperature tested to determine bypass leakage.
- **3.** The majority of the zones supply outlets are light troffers that do not have any balancing dampers. The adjusted CFM and zone manual balancing damper position is as follows.

| Zone No. | Design CFM | Actual CFM | Damper % Open |
|----------|------------|-------------|---------------|
| 1 | 5,950 | 5,665 (94%) | 100 |
| 3 | 1,000 | 785 (79%) | 80 |
| 6 | 1700 | 1,565 (92%) | 40 |
| 7 | 3,000 | 2,510 (84%) | 50 |
| 8 | 600 | 630 (105% | 70 |
| 9 | 2,520 | 1070 (42%) | 10 |
| 10 | 2,000 | 945 (47% | 20 |
| 11 | 2,000 | 1805 (86%) | 20 |
| 1B | 700 | 530 (76%) | 20 |
| | | | |

Adjusting any of the zone dampers will make a big change on the other zones. Essentially, requiring a complete system balance.

4. EF-53 and EF-54: Not operating. Electrical wiring to fans has been cut.

MATH & Science Building # 16:

- 1. Min OSA: We need required minimum OSA for MZ-8, AHU-1/1A, AHU-2.
- 2. MZ-8 Zone no. 5 Rm. 100F Hall 3 diffusers have fire dampers closed.
- 3. MZ-8 Zone no. 7 Rm. 100J Hall FSD closed.
- 4. MZ-8 Zone no. 7 Rm. 100F FSD closed.
- **5. MZ-8** Zone no. 1 Rm. mechanical FSD closed.
- **6. MZ-8** Zone no. 7 Rm. 100 E Hall 2 FSD closed.
- **7. TU-150** Fan motor not operating.
- 8. TU-154 Fan motor not operating.
- **9. TU-155** Fan motor not operating.
- **10. AHU-1/1A**: 1/3 of the FSD discharge duct serving 2nd Floor has failed closed.

- 11. EF-135: Fan not running.
- 12. EF-1 Belt broken
- 13. EF-2 Belts extremely loose.
- 14. TU-213 Fan not operating.
- **15. TU-204** Rm. 100J FSD closed.
- 16. TU-206 Fan motor not running.
- 17. TU-218 Rm. 2,000 Hall FSD closed.
- 18. TU-223 Rm. 227 Hall FSD closed.
- 19. TU-232 Rm. 200A Hall 3 FSDs closed.
- 20. TU-211 Rm. 232 Entry FSDs closed.
- 21. TU-215 Rm. 200A 4 FSDs closed.
- 22. TU-217 Rm. 200A 3 FSDs closed.
- 23. TU-216 Rm. 200A 3 FSDs closed.

Workforce Building # 19

- **1. TU-202C** Fan motor not operating.
- 2. TU-207C Fan motor not operating.
- 3. TU-204C TU controls not controlling to correct CFM
- 4. TU-213C TU controls not controlling to correct CFM.
- 5. TU-208 FSD closed
- 6. TU-213 TU controller not responding.
- 7. TU-206 TU not controlling to set point CFM.
- 8. TU-209B Fan not working.
- 9. TU-203B Controls not set up.
- 10. TU-204B Controls not set up.
- 11. TU-201B TU damper not working.
- 12. TU-220B TU not controlling.
- 13. TU-201C No control over TU box..
- 14. TU-104A FSD closed preventing airflow to opening.
- **15. TU-105A** Fan motor not operating.
- **16. TU-109A** Fan motor not operating.
- **17. TU-113A** Fan motor not operating.
- 18. TU-112A FSD primary air to TU-112A closed.
- 19. TU-112A FSD with supply to A114 is closed.
- 20. TU-208A FSD for primary air to TU-208A is closed.
- 21. TU-209A FSD for primary air to 209A is closed.
- 22. TU-210A Fan motor not running.
- 23. TU-211A Fan motor not operating.
- **24. TU-217A** FSD for primary air to YU-209A is closed.
- 25. TU-216A Fan motor burnt up.
- 26. TU-201C Fan controller not working, damper does not move.
- 27. TU-203C Fan motor not operating.
- 28. TU-208B Controls not set up.
- 29. TU-204B Controls not set up.
- **30. TU-201B** TU damper not working.
- 31. TU-220B TU not controlling.





AIR INTRODUCTION & REGULATION 90710 HUNTLEY COURT, COBURG, OR 97408 PHONE (541) 484-1928 | FAX (541) 343-6704

Health Technology Building #4

- 1. Min OSA need required minimum OSA for AHU 4.1.
- 2. VAV 1-218 damper will not go 100% open when commanded.

Physical Education #5

- 1. Need to test AHU-5.1, AHU-5.2, and AHU-5.3.
- 2. We have tested MZ-5.12, MZ-25, HV-5-6, HV-7, HV-8, & HV-9.
- 3. Toilet Rm. 113 design CFM is 350 actual is 105.
- **4.** Toilet Rm. 113B design CFM is 825 actual is 150.
- 5. Toilet Rm. 108 design CFM is 400 actual is 90.

Performing Arts # 6

- 1. Need design minimum OSA for AHU-1, MZ-22, MZ-23, HV-12, and HV-13.
- **2.** AHU-1 testing is complete.
- **3.** MZ-22 testing is complete.
- **4.** MZ-22 zone no.6 outlet is storage room 1151 id disconnected.
- **5.** MZ-23 needs to be tested.
- 6. HV-12 & HV-13 needs to be tested.

Auto Diesel #9

- 1. Need minimum OSA requirements for HV-1 & HV-2.
- 2. HV-1 & HV-2 need to be tested.

Manufacturing # 12

- 1. Need minimum OSA requirements for AHU-1 and HV-5.
- **2.** This building has not been tested.

Forum # 17

1. Need design min OSA requirements for MZ-9.